



⇒ Cabur (continua)

Dimensiones mm	Tarjeta													
	MG-CPM-03 41291 5x10	MG-CPM-03 41291 6x10	MG-CPM-04 41390 5x10	MG-CPM-10 46192 5x12	MG-CPM-12 46390 4,2x9	STF-10 42810 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15	CPM-10 36190 16,5 5x10	CPM-10 36192 16,5 5x12	CPM-10 36193 18 5x12
Borna	MG-CPM-03 41291 5x10	MG-CPM-03 41291 6x10	MG-CPM-04 41390 5x10	MG-CPM-10 46192 5x12	MG-CPM-12 46390 4,2x9	STF-10 42810 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15	CPM-10 36190 16,5 5x10	CPM-10 36192 16,5 5x12	CPM-10 36193 18 5x12
SCB.4/6...SCB.8/10/CD	C	C	C	C			C	C	S	S	P	C	P	C
AFO.2/1+1...AFO.2/2+2/TP	C	C	C	C			C	C	S	S	P	C	P	C
PDF.2	C	C	C	C			C	C	S	S	P	C	P	C
FDP.2	C	C	C	C			C	C	S	S	P	C	P	C
CVF.4/6...CVF.4/6/TP	C	C	C	C			C	C	S	S	P	C	P	C
TC/PO	S	S	P				S	S			S	S	S	
VPC.2/4	S	S	S				S	S			S	S	S	
GPM.95/BB...GPM.240/300/CC	C	C	C	C			C	C	C	C	C	C	C	C
GPA.70...GPA.240	C	C	C	C			C	C	C	C	C	C	C	C
ACB.70/BB...ACB.185/240/CC	C	C	C	C			C	C	C	C	C	C	C	C
BCA.70/BB...BCA.120/185/CC	C	C	C	C			C	C	C	C	C	C	C	C
MBL.50/6...MBL.150/12	C	C	C	C			C	C	C	C	C	C	C	C
TEO.2/4	S	S	P				S	S			S	S	S	
TEO.4/6	C	C	C				C	C	S	S	P	C	P	C
CBE.2/4	P	M	S				S	S			S	S	S	
TE.4/6/D...TE.50/D...TE.50/O	C	C	C	S			C	C	S	S	P	C	P	C
RN.1/2,5							C							
RN.2/4	P	M	S				S	S			S	S	S	
RP.4/6	C	C	C				C	C	S	S	C	C	C	C
RFL.2	C	C	C				C	C	S	S	C	C	C	C
TR.2/4	P	M	S				S	S			S	S	S	
TR.4/6	P	M	S				S	S			S	S	S	
MAC.6/10...MAC.6/10/N	C	C	CP	C			CP	CP	P	P	CP	CP	CP	CP
CAM...CAM/C	C	C	CP	C			CP	CP	P	P	CP	CP	CP	CP
NCS	C	C	C				C	C	S	S	C	C	C	C
NCV	C	C	C				C	C	S	S	C	C	C	C
CNT.6...CNT.35	C	P	C				CP	CP	CP	CP	C	P	C	P
HMM.1/2,5...HMM.1/2,5/2+2					P	M								
HMM.2/4...HMM.6/10					C	M								
HTE.2/4...HTE.6/10					C									
HMD.2N...HMD.2/4					C	P								
HMS.2/4					C									
HMF.4/6...HMF.4/6/115					C									
EDM.2/4	S	S	P				S	S						
EDM.4/6...EDM.70/50/BC	C	C					C	C			C	C		
SV.2...SV.2/VS	S	S	P				S	S						
SV.4/6...SV.10/16	C	C	C				C	C	C	C	C	C		
CPS.4/6	C	C	C				C	C	C	C	C	C		
SCX.10/16...SCX.10/16-PI	C	C	C				C	C	C	C	C	C		
SFC.10/16	C	C	C				C	C	C	C	C	C		
SFL.10/16	C	C	C				C	C	C	C	C	C		
FLD.10/16/F5...FLD.10/16/D	C	C	C				C	C	C	C	C	C		
VLM.10/16...VLM.10/16/O	C	C	C				C	C	C	C	C	C		
VL.16...VL.16/O-M	C	C	C				C	C	C	C	C	C		
TC/DIN	S	S	P				S	S						
VNF.6/10...VNF.6/10/STP	C	C	C				C	C	C	C	C	C		
CDA.70/BC...CDA.185/BB	C	C	C				C	C	C	C	C	C		
BTU	C	C	P				C	C	C	C	C	CP	C	CP
BT/3	C	C	P				C	C	C	C	C	CP	C	CP
BT/2	C	C	P				C	C	C	C	C	CP	C	CP
BT/DIN/PO	C	C	P				C	C	C	C	C	CP	C	CP

Conta Clip

Dimensiones mm	Tarjeta												
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-02 41190 5x10	MG-CPM-01 41094 5x7	STF-01 42801 6,3x105	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-11 36290 5x9	CPM-11 36291 6x9	CPM-11 36293 6x12
Borna	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-02 41190 5x10	MG-CPM-01 41094 5x7	STF-01 42801 6,3x105	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-11 36290 5x9	CPM-11 36291 6x9	CPM-11 36293 6x12
PK-TS 15/35	C	C	C	M	C	C	C	C	C	C	C	C	C
ZRKG	C	C	C	M	C	C	C	C	C	C	C	C	C
ZSLG	C	C	C	M	C	C	C	C	C	C	C	C	C
ZSLN	C	C	C	M	C	C	C	C	C	C	C	C	C
ZSRK	C	C	C	M	C	C	C	C	C	C	C	C	C
ZVMAK	C	C	C	M	C	C	C	C	C	C	C	C	C

Phoenix Contact

Dimensiones mm	Tarjeta										
	MG-CPM-03 41291 5x10	MG-CPM-04 41390 5x10	MG-CPM-04 41395 5x10	MG-CPM-07 41691 5x10	STF-04 42804 6,3x105	MG-CPMF 43092 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
Borna	MG-CPM-03 41291 5x10	MG-CPM-04 41390 5x10	MG-CPM-04 41395 5x10	MG-CPM-07 41691 5x10	STF-04 42804 6,3x105	MG-CPMF 43092 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
ASIO SL DI 4/4	C	C		M				C			
ASIO SL DIO 4/2/2	C	C		M				C			
ASIO SL DIO 8/4/4	C	C		M				C			
ASIO SL DO 4/4	C	C		M				C			

⇒ Phoenix Contact (continua)

Dimensiones mm	Tarjeta										
	MG-CPM-03 41291 5x10	MG-CPM-04 41390 5x10	MG-CPM-04 41395 5x10	MG-CPM-07 41691 5x10	STF-04 42804 6,3x105	MG-CPMF 43092 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
Borna	MG-CPM-03 41291 5x10	MG-CPM-04 41390 5x10	MG-CPM-04 41395 5x10	MG-CPM-07 41691 5x10	STF-04 42804 6,3x105	MG-CPMF 43092 6,3x105	CPM-03 31290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
DFK ...	C	C				M		C	C	S	S
DFK 4	C	C				M		C	C	S	S
DFK 4 - PE	C	C				M		C	C	S	S
DFK 4 - SI	C	C				M		C	C	S	S
DIK 1.5	C	C				M		C	C	S	S
DIK 1.5 - LA (RD)	C	C				M		C	C	S	S
DIKD 1.5	C	C				M		C	C	S	S
DIKD 1.5 - LA	C	C				M		C	C	S	S
DIKD 1.5 - PV	C	C				M		C	C	S	S
DLK 2.5 - PE	C	C				M		C	C	S	S
DLK 2.5 PE	C	C				M		C	C	S	S
DOK 1.5 - 2D	C	C				M		C	C	S	S
DOK 1.5 LA	C	C				M		C	C	S	S
DOK 1.5 TG	C	C				M		C	C	S	S
DOKD 1.5 - TG	C	C				M		C	C	S	S
E - UK	C	C				M		C	C	S	S
GBS 5-UK/B	S	S	M			M		S	S		
GTf 76/230	C	C				M		C	C	C	C
IBIL ...	C	C				M		C	C	C	C
K4 - SP	C	C	M			M		C	C	C	C
MBK 3/ E - Z	S	S	M			M		S	S		
MBK 3/ E - Z - PE	S	S	M			M		S	S		
MBK 6 / E	C	C	M			M		C	C	C	C
MBKKB 2.5	S	S	M			M		S	S		
MBKKB 2.5 - DIO	S	S	M			M		S	S		
MBKKB 2.5 - PV	S	S	M			M		S	S		
MBKKB 2.5 + V	S	S	M			M		S	S		
MBT 2.5	C	C				M		C	C	S	S
MBT 2.5 PE	C	C				M		C	C	S	S
MSLKG 6	C	C				M		C	C	S	S
MT 1.5								S			
MT 1.5 PE								S			
MT 1.5 QUATTRO								S			
MT 1.5 QUATTRO - PE								S			
MT 1.5 TWIN								S			
MT 1.5 TWIN - PE								S			
MTK - LOE	S	S	M			M		S	S		
MTK - P/P	S	S	M			M		S	S		
MTK - TP	S	S	M			M		S	S		
MTKD...	C	C				M		C	C	C	C
MTTB 1.5											
OTTA 2.5	C	C				M		C	C	C	C
OTTA											

⇒ Phoenix Contact (continua)

Dimensiones mm	Tarjeta						Borna				
	5x10	5x10	5x10	5x10	6x10	6x15					
	MG-CPM-03 41291	MG-CPM-04 41390	MG-CPM-04 41395	MG-CPM-07 41691	STF-04 42804 <sub>4bornos</sub>	MG-CPMF 43092	CPM-03 31290 3x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
UDMTX 5 - TWIN - P/P	C	C		M			C	C	S	S	
UHSK / S 2000	C	C		M			C	C	S	S	
UHV 25	C	C		M			C	C	S	S	
UHV 50	C	C		M			C	C	S	S	
UHV 95	C	C		M			C	C	S	S	
UHV 150	C	C		M			C	C	S	S	
UHV 240	C	C		M			C	C	S	S	
UIK 16	C	C		M			C	C	S	S	
UIK 16 - PE / N	C	C		M			C	C	S	S	
UIK 35 - PE / N	C	C		M			C	C	S	S	
UIKN 35	C	C		M			C	C	S	S	
UISLKG 16	C	C		M			C	C	S	S	
UISLKG 35	C	C		M			C	C	S	S	
UK - FRONT 4	C	C		M			C	C	S	S	
UK - FRONT 4 - PE	C	C		M			C	C	S	S	
UK 1.5 N							S				
UK 2.5	S	S	M	M			S	S			
UK 2.5 B	C	C		M			C	C	S	S	
UK 2.5 LOER	C	C		M			C	C	S	S	
UK 2.5 N	S	S	M	M			S	S			
UK 3	S	S	M	M			S	S			
UK 3 - EX	S	S	M	M			S	S			
UK 3 - RETURN	S	S	M	M			S	S			
UK 3 - RETURN - PE	S	S	M	M			S	S			
UK 3 - TWIN	S	S	M	M			S	S			
UK 3 - TWIN - PE	S	S	M	M			S	S			
UK 3 N	S	S	M	M			S	S			
UK 4	C	C		M			C	C	S	S	
UK 4 - TG	C	C		M			C	C	S	S	
UK 4 - TG-LOER - P/P	C	C		M			C	C	S	S	
UK 4 FS / FS	C	C		M			C	C	S	S	
UK 4 FSR	C	C		M			C	C	S	S	
UK 4 LOER	C	C		M			C	C	S	S	
UK 4 TP	C	C		M			C	C	S	S	
UK 4 TP / TP	C	C		M			C	C	S	S	
UK 5	C	C		M			C	C	S	S	
UK 5 - HESI	C	C		M			C	C	S	S	
UK 5 - MTK - P/P	C	C		M			C	C	S	S	
UK 5 - R - L	C	C		M			C	C	S	S	
UK 5 - TWIN	C	C		M			C	C			
UK 5 - TWIN - EX	C	C		M			C	C			
UK 5 / R - DRAHT	C	C		M			C	C	S	S	
UK 5 N	C	C		M			C	C	S	S	
UK 5 RETURN	C	C		M			C	C	S	S	
UK 5 RETURN - PE	C	C		M			C	C	S	S	
UK 5 TWIN	C	C		M			C	C	S	S	
UK 5 TWIN - PE	C	C		M			C	C	S	S	
UK 6	C	C		M			C	C	C	C	
UK 6 N	C	C		M			C	C	C	C	
UK 6.3 HESI	C	C		M			C	C	C	C	
UK 10	C	C		M			C	C	C	C	
UK 10 - DREHSI	C	C		M			C	C	C	C	
UK 10 - EX	C	C		M			C	C	C	C	
UK 10 - N-PE / N	C	C		M			C	C	C	C	
UK 10 - PLUS	C	C		M			C	C	C	C	
UK 10 - PLUS - PE	C	C		M			C	C	C	C	
UK 10 - TWIN	C	C		M			C	C	C	C	
UK 10 - TWIN - PE	C	C		M			C	C	C	C	
UK 10 N	C	C		M			C	C	C	C	
UK 10 RETURN	C	C		M			C	C	C	C	
UK 10 RETURN - PE	C	C		M			C	C	C	C	
UK 10.3 - HESI	C	C		M			C	C	C	C	
UK 16	C	C		M			C	C	C	C	
UK 16 - EX	C	C		M			C	C	C	C	
UK 16 - PE / N	C	C		M			C	C	C	C	
UK 16 N	C	C		M			C	C	C	C	
UK 16 N - EX	C	C		M			C	C	C	C	
UK 16 N - PE / N	C	C		M			C	C	C	C	
UK 35	C	C		M			C	C	C	C	
UK 35 - EX	C	C		M			C	C	C	C	
UK 35 - PE / N	C	C		M			C	C	C	C	
UK SI	C	C		M			C	C	C	C	
UKB 4 FS ...	C	C		M			C	C	S		
UKD 4 PE	C	C		M			C	C	C		
UKH 25	C	C		M			C	C	C		
UKH 50	C	C		M			C	C	C		
UKH 50 - PE / N	C	C		M			C	C	C		
UKH 95	C	C		M			C	C	C		
UKH 95 - PE / N	C	C		M			C	C	C		
UKH 150	C	C		M			C	C	C		
UKH 240	C	C		M			C	C	C		
UKK 3	S	S		M			S	S			

⇒ Phoenix Contact (continua)

Dimensiones mm	Tarjeta						Borna				
	5x10	5x10	5x10	5x10	6x10	6x15					
	MG-CPM-03 41291	MG-CPM-04 41390	MG-CPM-04 41395	MG-CPM-07 41691	STF-04 42804 <sub>4bornos</sub>	MG-CPMF 43092	CPM-03 31290 3x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15
UKK 4 - FS	C	C		M			C	C	S	S	
UKK 4 - FS / FS	C	C		M			C	C	S	S	
UKK 5	C	C		M			C	C	C	C	
UKK 5 - DIO	C	C		M			C	C	C	C	
UKK 5 - TG	C	C		M			C	C	C	C	
UKK 5 - 2-DIO	C	C		M			C	C	C	C	
UKK 5 - LA	C	C		M			C	C	S	S	
UKKB 3	S	S	M	M			S	S			
UKKB 5	C	C		M			C	C	S	S	
UKKB 10	C	C		M			C	C	C	C	
UKKB 10 / 2.5	C	C		M			C	C	C	C	
UKKB 10 / 2.5 - PE	C	C		M			C	C	C	C	
UKN 2.5	C	C		M			C	C	S	S	
UKN 4	C	C		M			C	C	S	S	
UKN 5	C	C		M			C	C	S	S	
UKN 10 (N)	C	C		M			C	C	C	C	
UKN 16	C	C		M			C	C	C	C	
UKN 16N	C	C		M			C	C	C	C	
UKN 35	C	C		M			C	C	C	C	
UKSN	C	C		M			C	C	C	C	
URK - ND	C	C		M			C	C	C	C	
URK - ND 2	C	C		M			C	C	C	C	
URKN	C	C		M			C	C	C	C	
URKN - A	C	C		M			C	C	C	C	
URKN / S	C	C		M			C	C	C	C	
URTK - BEN	C	C		M			C	C	C	C	
URTK / S	C	C		M			C	C	C	C	
URTK / S - BEN	C	C		M			C	C	C	C	
URTK / SS	C	C		M			C	C	C	C	
URTKD / SP	C	C		M			C	C	C	C	
USED 16	C	C		M			C	C	C	C	
USED 27	C	C		M			C	C	C	C	
USEN 14	C	C		M			C	C	C	C	
USEN 18	C	C		M			C	C	C	C	
USK / SGSK	C	C		M			C	C	C	C	
USK 4 FSR...	C	C		M			C	C	C	C	
USLKG 2.5	S	S		M			S	S			
USLKG 2.5 - N	S	S		M			S	S			
USLKG 3	S	S		M			S	S			
USLKG 4	C	C		M			C	C	S	S	
USLKG 5	C	C		M			C	C	S	S	
USLKG 10 (N)	C	C		M			C	C	C	C	
USLKG 16	C	C		M			C	C	C	C	
USLKG 16 N	C	C		M			C	C	C	C	
USLKG 35	C	C		M			C	C	C	C	
USLKG 50	C	C		M			C	C	C	C	
USLKG 95	C	C		M			C	C	C	C	
UT 4	C	C		M			C	C	S	S	
UT 4 BU	C	C		M			C	C	S	S	
UT 4 YE	C	C		M			C	C	S	S	
UT 4-MTD BU	C	C		M			C	C	S	S	
UT 4-MTD-PE	C	C		M			C	C	S	S	
UTK 35	C	C		M			C	C	S	S	
UXKK 4	C	C		M			C	C	S	S	
VBSN 4 FS ...	C	C		M			C	C	S		
VBST 4 FS / FS	C	C		M			C	C	S		
VIOK 1.5	C	C		M			C	C	S		
VIOK 1.5-2D	C	C		M			C	C	S		
VIOK 1.5-3D/PE	C	C		M			C	C	S		
VIOK 1.5-D/TG/D/PE	C	C		M			C	C	S		
VIOK 1.5-LA	C	C		M			C	C	S		
ZFDK 2.5	C	C		M			C	C			
ZFDK -PE	C	C		M			C	C			
ZFK 1.5							S				
ZFK 2.5 - PE	C	C		M			C	C			
ZFK 2.5 - PE / L / N	C	C		M			C	C	S		
ZFK 2.5 - TWIN	C	C		M			C	C			
ZFK 2.5 - TWIN - PE	C	C		M			C	C			
ZFK 4	C	C		M			C	C	S		
ZFK 4 - PE	C	C		M			C	C	S		
ZFK 4 - TG	C	C		M			C	C	S		
ZFK 6	C	C		M			C	C	C		
ZFK 16	C	C		M			C	C	C		
ZFK 14	C	C		M			C	C	C		
ZFKK 2.5 (-MT)	C	C		M			C	C			
ZFKN 4	C	C		M			C	C			

Schlegel

A confirmar

Siemens

	Dimensiones mm				Tarjeta
	5x10	5x15	5x7	5x10	
<b>Borna</b>	MG-CPM-06 4191	SIF-04 4280 4 pines	CPM-06 3190	CPM-06 3191	
8WA1 011-ODF21	S	M	S	S	
8WA1 011-ODG21	S	M	S	S	
8WA1 011-1BF23	S	M	S	S	
8WA1 011-IDF11	S	M	S	S	
8WA1 011-IDG11	S	M	S	S	
8WA1 011-2DG11	S	M	S	S	
8WA1 011-3DF21	S	M	S	S	
8WA1 011-3DG21	S	M	S	S	
8WA1 011-IDH11	S	M	S	S	
8WA1 221	S	M	S	S	
8WA1 741-2X	S	M	S	S	
8WA1... / 8WA2...	S		S		
8WA2 011-IDF20	S	M	S	S	
8WA2 011-IDG20	S	S	S	S	
8WA2 011-IDH20	S	S	S	S	

Wago

	Dimensiones mm				Tarjeta																	
	5x10	5x15	5x7	5x10																		
<b>Borna</b>	MG-CPM-01 41090	MG-CPM-01 41091	MG-CPM-01 41094	MG-CPM-02 41190	MG-CPM-03 41291	MG-CPM-03 41293	MG-CPM-04 41390	MG-CPM-12 46390	SIF pines	MG-CPMF 43093	MG-CPMF 43095	MG-YYB 16090	CPM-01 31090	CPM-01 31091	CPM-01 31092	CPM-01 31093	CPM-02 31190	CPM-03 36290	CPM-04 31390	CPM-08 31790	CPM-12 6x12	
Top-Job 2000			C						MF													
Top-Job 2001			C						MF				S	S								
Top-Job 2002	S	S	C	S					MF	M	M		S	S	S			S				S
Top-Job 2004	C	C	C	C					MF	M	M		C	C	S	S		C				
260-...												M										
261-...												M										
262-...												M										
264-...										M												
279-104																						S
279-105																						S
279-106																						S
279-107																						S
279-108																						S
279-109																						S
279-110																						S
279-111																						S
279-112																						S
279-113																						S
279-114																						S
279-115																						S
279-116																						S
279-117																						S
279-118																						S
279-119																						S
279-120																						S
279-121																						S
279-122																						S
279-123																						S
279-124																						S
279-125																						S
279-126																						S
279-127																						S
279-128																						S
279-129																						S
279-130																						S
279-131																						S
279-132																						S
280-520				P	M	C				M												S
280-560				P	M	C				M												S
280-601				P	M	C				M												S
280-607				P	M	C				M												S
280-612				P	M	C				M												S
280-622				P	M	C				M												S
280-626				P	M	C				M												S
280-641				P	M	C				M												S
280-646				P	M	C				M												S
280-649				P	M	C				M												S
280-650				P	M	C				M												S
280-651				P	M	C				M												S
280-653				P	M	C				M												S
280-654				P	M	C				M												S
280-656				P	M	C				M												S
280-671				P	M	C				M												S
280-672				P	M	C				M												S
280-676				P	M	C				M												S
280-681				P	M	C				M												S
280-683				P	M	C				M												S

Wago (continua)

	Dimensiones mm				Tarjeta																		
	5x10	5x15	5x7	5x10																			
<b>Borna</b>	MG-CPM-01 41090	MG-CPM-01 41091	MG-CPM-01 41094	MG-CPM-02 41190	MG-CPM-03 41291	MG-CPM-03 41293	MG-CPM-04 41390	MG-CPM-12 46390	4,2x9	SIF pines	MG-CPMF 43093	CPM-01 31090	CPM-01 31091	CPM-01 31092	CPM-01 31093	CPM-02 31190	CPM-03 36290	CPM-04 31390	CPM-04 31391	CPM-04 31392	CPM-04 31393	CPM-08 31790	CPM-12 6x12
280-684					P	M	C			M												S	S
280-685					P	M	C			M												S	S
280-687					P	M	C			M												S	S
280-695					P	M	C			M												S	S
280-830					P	M	C			M												S	S
280-831					P	M	C			M												S	S
280-832					P	M	C			M												S	S
280-833					P	M	C			M												S	S
280-834					P	M	C			M												S	S
280-835					P	M	C			M												S	S
280-836					P	M	C			M												S	S
280-837					P	M	C			M												S	S
280-869					P	M	C			M												S	S
280-870					P	M	C			M												S	S
280-871					P	M	C			M												S	S
280-874					P	M	C			M												S	S
280-875					P	M	C			M												S	S
280-876					P	M	C			M												S	S
280-878					P																		

⇒ Wago (continua)

Dimensiones mm	Tarijeta																						
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-01 41094 5x7	MG-CPM-02 41190 5x10	MG-CPM-03 41291 5x10	MG-CPM-03 41293 5x10	MG-CPM-04 41390 5x10	MG-CPM-12 46390 4,2x9	STF abras	MG-CPMF 43093 10,5x105	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-03 36290 3,9x10	CPM-04 31390 5x10	CPM-04 31391 5x15	CPM-04 31392 6x10	CPM-04 31393 6x15	CPM-08 31790 6x12		
Borna																							
283-677					C	C	M										C	C	C	C			
283-901					C	C	M										C	C	C	C			
283-902					C	C	M										C	C	C	C			
283-904					C	C	M										C	C	C	C			
283-907					C	C	M										C	C	C	C			
284-601					C	C	M										C	C	C	C			
284-604					C	C	M										C	C	C	C			
284-607					C	C	M										C	C	C	C			
284-681					C	C	M										C	C	C	C			
284-682					C	C	M										C	C	C	C			
284-684					C	C	M										C	C	C	C			
284-687					C	C	M										C	C	C	C			
284-901					C	C	M										C	C	C	C			
284-902					C	C	M										C	C	C	C			
284-904					C	C	M										C	C	C	C			
284-907					C	C	M										C	C	C	C			
285-601					C	C	M										C	C	C	C			
285-605					C	C	M										C	C	C	C			
290-681				P	M	C											S	S					
750-xxx	S	S	C	S				M	S	S		S											
769-237	S	S	C	S				M	S	S		S											
775-641									S	S		S											
777-641																	C	C	S	S			
870-501	S	C	S					M	S			S											
870-507	S	C	S					M	S			S											
870-531	S	C	S					M	S			S											
870-538	S	C	S					M	S			S											
870-551	S	C	S					M	S			S											
870-567	S	C	S					M	S			S											
870-831	S	C	S					M	S			S											
870-901	S	C	S					M	S			S											
880-901	S	C	S	P	M	S		M	S			S											

Weidmüller

Dimensiones mm	Tarijeta															
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-01 41094 5x7	MG-CPM-02 41190 5x10	STF-01 42801 abras	MG-CPMF 43094 5,2x105	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-08 31790 6x12	CPM-11 36291 5x12	CPM-11 36292 6x9	CPM-11 36293 6x12	
Borna																
AKZ 4./AKB 4...	C	C	C	M			C	C	S	S	C					
DIA 2.5	C	C	C	M			C	C	S	S	C	C	C			
DID 2.5	C	C	C	M			C	C	S	S	C	C	C			
DUI 2.5	C	C	C	M			C	C	S	S	C	C	C			
EK 2.5	C	C	C	M			C	C	S	S	C	C	C			
EK 6	CP	CP	CP	CP	M		CP	CP	CP	CP	CP	CP	CP			
EK 10	C	C	C	M			C	C	S	S	C	C	C			
EK 16	C	C	C	M			C	C	S	S	C	C	C			
EK 35	C	C	C	M			C	C	S	S	C	C	C			
EW15	C	C	C	M			C	C	S	S	C	C	C			
EW35	C	C	C	M			C	C	S	S	C	C	C			
EWK1	C	C	C	M			C	C	S	S	C	C	C			
EWK2	C	C	C	M			C	C	S	S	C	C	C			
IAK 1.5N 3L	S	S	S	M			S	S			S					
IDK 1.5	S	S	S	M			S	S			S					
IDK 1.5N	S	S	S	M			S	S			S					
IDK 1.5N/V	S	S	S	M			S	S			S					
IDU 1.5N	S	S	S	M			S	S			S					
IDU 2.5N	C	C	C	M			C	C	S	S	C	C				
IEK 1.5N	S	S	S	M			S	S			S					
IHK 1.5N	S	S	S	M			S	S			S					
IPE 1.5N	S	S	S	M			S	S			S					
IPE 2.5N	C	C	C	M			C	C	S	S	C	C				
ITR 1.5N	S	S	S	M			S	S			S					
MAK 2.5	C	C	C	M			C	C	S	S	C	C				
Mak 2.5/VII 1.5	C	C	C	M			C	C	S	S	C	C				
NT 4	C	C	C	M			C	C	S	S	C	CP				
NT 6	CP	CP	CP	CP	M		CP	CP	CP	CP	CP	CP				
NT 10	C	C	C	M			C	C	S	S	C	C				
NT 16	C	C	C	M			C	C	S	S	C	C				
SAI-M16 / M23 in SAI-M8	C	C	C	M			C	C	S	S	C	C				
SAK 2.5	C	C	C	M			C	C	S	S	C	CP				
SAK 4	C	C	C	M			C	C	S	S	C	C				
SAK 6	CP	CP	CP	CP	M		CP	CP	CP	CP	CP	CP				
SAK 10 (PA)	C	C	C	M			C	C	S	S	C	C				
SAK 16	C	C	C	M			C	C	S	S	C	C				
SAK 35	C	C	C	M			C	C	S	S	C	C				
SAK 70	C	C	C	M			C	C	S	S	C	C				
SAK 95	C	C	C	M			C	C	S	S	C	C				
SAKA 10	C	C	C	M			C	C	S	S	C	C				

⇒ Weidmüller (continua)

Dimensiones mm	Tarijeta																
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-01 41094 5x7	MG-CPM-02 41190 5x10	STF-01 42801 abras	MG-CPMF 43094 5,2x105	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-08 31790 6x12	CPM-11 36290 5x9	CPM-11 36291 5x12	CPM-11 36292 6x9	CPM-11 36293 6x12	
Borna																	
SAKB 10	C	C	C	M			C	C	S	S	C	C					
SAKC 4	C	C	C	M			C	C	S	S	C	C					
SAKC 10	C	C	C	M			C	C	S	S	C	C					
SAKD 2.5 N	S	S	S	M			S	S			S	C					
SAKG 28	C	C	C	M			C	C	S	S	C	C					
SAKG 32	C	C	C	M			C	C	S	S	C	C					
SAKG 40	C	C	C	M			C	C	S	S	C	C					
SAKG 46	C	C	C	M			C	C	S	S	C	C					
SAKG 54	C	C	C	M			C	C	S	S	C	C					
SAKG 70	C	C	C	M			C	C	S	S	C	C					
SAKR	C	C	C	M			C	C	S	S	C	C					
SAKRD	C	C	C	M			C	C	S	S	C	C					
SAKS 1	C	C	C	M			C	C	S	S	C	C					
SAKS 2	C	C	C	M			C	C	S	S	C	C					
SAKS 3	C	C	C	M			C	C	S	S	C	C					
SAKS 4	C	C	C	M			C	C	S	S	C	C					
SAKS 5	C	C	C	M			C	C	S	S	C	C					
SAKT 1	CP	CP	CP	CP	M		CP	CP	CP	CP	CP	CP					
SAKT 2	CP	CP	CP	CP	M		CP	CP	CP	CP	CP	CP					
SAKT 4	C	C	C	M			C	C	S	S	C	CP					
SCHTS																	
SCHTSS																	
SS 6	C	C	C	M			C	C	S	S	C						
SS 8	C	C	C	M			C	C	S	S	C						
SS 10	C	C	C	M			C	C	S	S	C						
SS 12	C	C	C	M			C	C	S	S	C						
TOP 2.5	C	C	C	M			C	C	S	S	C						
TOP 4	C	C	C	M			C	C	S	S	C						
VLI 2.5	C	C	C	M			C	C	S	S	C						
WDK 2.5	S	S	S	M			S	S			S	C					
WDK 2.5 800V	C	C	C	M			C	C	S	S	C	C					
WDK 2.5 BLA R5.08	S	S	S	M			S	S			S	C					
WDK 2.5 BLZ R5.08	S	S	S	M			S	S			S	C					
WDK 2.5N	S	S	S	M			S	S			S	C					
WDK 4N	C	C	C	M			C	C	S	S	C	C					
WDL 2.5	C	C	C	M			C	C	S	S	C	C					
WDL 2.5 / S	C	C	C	M			C										

⇒ Weidmüller (continua)

Borna	Dimensiones mm															
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-01 41094 5x7	MG-CPM-02 41190 5x10	STF-01 42801 6x0,85	MG-CPMF 43094 5,2x105 5x10	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-08 31790 6x12	CPM-11 36290 5x9	CPM-11 36291 5x12	CPM-11 36292 6x9	CPM-11 36293 6x12
WSI 6	C	C	C	C	M	C	C	C	C	C						
WSI 6/2	C	C	C	C	M	C	C	C	C	C						
WTL 6/1	C	C	C	C	M	C	C	C	C	C						
WTL 6/2	CP	CP	CP	CP	M	CP	CP	CP	CP	CP						
WTR 2.5	C	C	C	C	M	C	C	C	C							
ZBD 2.5/1.5	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5 DU-PE	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5 N-PE	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5 V / E	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5/E	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5/E BL	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5/LD/1	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5/LD/2	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5/N-PE/E	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5DU...6	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5N-DU	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5N-DU/E	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5N-DU-PE/E	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5PE	C	C	C	C	M	C	C	C	C							
ZDK 2.5/1.5V	C	C	C	C	M	C	C	C	C							
ZDKB	C	C	C	C	M	C	C	C	C							
ZDKS	C	C	C	C	M	C	C	C	C							
ZDID 2.5 / 1.5	C	C	C	C	M	C	C	C	C							
ZDID 2.5 / 1.5 V	C	C	C	C	M	C	C	C	C							
ZDU 1.5					M											
ZDU 2.5 2.5/10	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN /E/ BL	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN/10	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN/D	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN/E	C	C	C	C	M	C	C			C						
ZDU 2.5/2x2AN/LD	C	C	C	C	M	C	C			C						
ZDU 2.5/3AN	C	C	C	C	M	C	C		C							
ZDU 2.5/3AN /E/ BL	C	C	C	C	M	C	C		C							
ZDU 2.5/3AN/10	C	C	C	C	M	C	C		C							
ZDU 2.5/3AN/E	C	C	C	C	M	C	C		C							
ZDU 2.5/4AN	C	C	C	C	M	C	C		C							
ZDU 2.5/4AN /E/ BL	C	C	C	C	M	C	C		C							
ZDU 2.5/4AN/10	C	C	C	C	M	C	C		C							
ZDU 2.5-2/3	C	C	C	C	M	C	C		C							
ZDU 2.5-2/3AN /E/ BL	C	C	C	C	M	C	C		C							
ZDU 2.5-2/4AN /E/	C	C	C	C	M	C	C		C							
ZDU 2.5-2/4AN /E/ BL	C	C	C	C	M	C	C		C							
ZDU 2.5 /E/	C	C	C	C	M	C	C		C							
ZDU 2.5 /E/ BL	C	C	C	C	M	C	C		C							
ZDU 2.5-2	C	C	C	C	M	C	C		C							
ZDU 4	C	C	C	C	M	C	C		S	CP						
ZDU 6	CP	CP	CP	CP	M	CP	CP		CP							
ZDU 10 NT	C	C	C	C	M	C	C			C						
ZDU 16 16/3AN	C	C	C	C	M	C	C			C						
ZDU 35	C	C	C	C	M	C	C			C						
ZDUA 2.5-2 /E/	C	C	C	C	M	C	C			C						
ZDUA 2.5-2 /E/ BL	C	C	C	C	M	C	C			C						
ZDUB 2.5 / 2/2/4AN	C	C	C	C	M	C	C			C						
ZDUB 2.5 / 2AN	C	C	C	C	M	C	C			C						
ZDUB 2.5-2/2AN	C	C	C	C	M	C	C			C						
ZIA 1.5/...	C	C	C	C	M	C	C		C							
ZK3S	C	C	C	C	M	C	C			C						
ZKB	C	C	C	C	M	C	C			C						
ZKS	C	C	C	C	M	C	C			C						
ZPE 2.5/4AN	C	C	C	C	M	C	C		C							
ZPE 2.5	C	C	C	C	M	C	C			C						
ZPE 2.5/3AN	C	C	C	C	M	C	C			C						
ZPE 2.5/3AN/E	C	C	C	C	M	C	C			C						
ZPE 2.5/4AN	C	C	C	C	M	C	C			C						
ZPE 2.5/4AN/E	C	C	C	C	M	C	C			C						
ZPE 2.5/E	C	C	C	C	M	C	C			C						

⇒ Weidmüller (continua)

Borna	Dimensiones mm														
	MG-CPM-01 41090 5x10	MG-CPM-01 41091 5x15	MG-CPM-01 41094 5x7	MG-CPM-02 41190 5x10	STF-01 42801 6x0,85	CPM-01 31090 5x10	CPM-01 31091 5x15	CPM-01 31092 6x10	CPM-01 31093 6x15	CPM-02 31190 5x10	CPM-08 31790 6x12	CPM-11 36290 5x9	CPM-11 36291 5x12	CPM-11 36292 6x9	CPM-11 36293 6x12
ZPE 2.5-2 /E/	C	C	C	C	M	C	C			C					
ZPE 2.5-2/3AN	C	C	C	C	M	C	C		C						
ZPE 2.5-2/3AN/E	C	C	C	C	M	C	C		C						
ZPE 2.5-2/4AN	C	C	C	C	M	C	C		C						
ZPE 35	C	C	C	C	M	C	C		C						
ZPEA-2/E	C	C	C	C	M	C	C		C						
ZRV 1.5	C	C	C	C	M	C	C		C						
ZRV 1.5PE	C	C	C	C	M	C	C		C						
ZSI 2.5	C	C	C	C	M	C	C			C					
ZSI 2.5/2	C	C	C	C	M	C	C			C					
ZSID 2.5/1.5	C	C	C	C	M	C	C			C					
ZTR 2.5	C	C	C	C	M	C	C		C						
ZTR 2.5 D	C	C	C	C	M	C	C		C						
ZTR 2.5/3AN	C	C	C	C	M	C	C		C						
ZVL 1.5 ....	C	C	C	C	M	C	C		C						

Wieland

Borna	Dimensiones mm						
	MG-CPM-05 41490 5x10	MG-CPM-05 41494 5x10	STF-05 42805 6x0,85	CPM-05 31490 5x10	CPM-05 31491 5x15	CPM-05 31492 6x10	CPM-05 31493 6x15
WK 2,5/ U	P	M	M	S	S		
WK 4/ U	C	C	M	C	C	C	C
WK 6/ U	C	C	M	CP	CP	CP	CP
WK 8/ U	C	C	M	C	C	C	C
WK 10/ U	C	C	M	C	C	C	C
WK 25/ U	C	C	M	C	C	C	C
WK 35/ U	C	C	M	C	C	C	C

Woertz

Borna	Dimensiones mm									
	MG-CPM-01 41090 5x10	MG-CPM-02 41190 5x10	MG-CPM-01 41094 5x7	CPM-01 31090 5x10	CPM-01 31092 6x10	CPM-02 31190 5x10	CPM-08 31790 6x12	CPM-11 36290 5x9	CPM-11 36292 6x9	CPM-11 36293 6x12
30150BL									S	
30150E									S	
30150GR									S	
30400									S	
30401									S	
30402									S	
30403									S	
30404									S	
30405									S	
30430									S	
30431									CP	P
30432									CP	P
30433									CP	P
30434									CP	P
30544 / 4 V	C	C	C	C	C	C	S	CP	CP	P
30544 / 6 V	C	C	C	C	C	C	C	C	C	C
30544 / 10 V	CP	CP	CP	CP	CP	CP	C	C	C	C
30800	C	C	C	C	C	C	S	CP	CP	P
30840	C	C	C	C	C	C	C	C	C	C
30841	C	C	C	C	C	C	C	C	C	C
30842	C	C	C	C	C	C	C	C	C	C
30843	C	C	C	C	C	C	C	C	C	C
30844	C	C	C	C	C	C	C	C	C	C
30860									S	
30880									C	
30890									CP	P
30891									CP	P
3410									CP	C
3430									CP	P
3450BL									C	C
3450GR									C	C